WIRING & MOUNTING SKETCH

WIRING DIAGRAM

C-SC Low Temperature Series



*Note: Thermal Overload Relay is required and the current setting is 18A .

MOUNTING SKETCH