WIRING DIAGRAM

C-SB/C Series 3 phase